Cumberland Valley School District



June 2, 2017









05/22/17 – Lobar subcontractor placed stone subbase and Lobar installed vapor barrier in Area A-East











05/24/17 – Lobar placed the concrete slab on grade in the North classrooms and wing corridor of Area A-East









05/24/17 – Lobar finished the concrete slab on grade in the North classrooms and wing corridor of Area A-East











05/30/17 – Lobar placed the concrete slab on grade in the South classrooms and stairwell of Area A-East









05/30/17 – Lobar finished the concrete slab on grade in the South classrooms and stairwell of Area A-East









05/22/17 – Lobar subcontractor excavated footers for Area A-West









05/24/17 – Lobar subcontractor placing CMU foundation walls for Area A-West









05/22/17 – Boro continued install of underground feeder conduit from Area A Electric Room towards main electrical room in Area C









05/26/17 – Silvertip installed underground sanitary piping in Area B1 restroom pipe chase







Boro complete with under slab conduit and Silvertip complete with underground piping in Area B1 ahead of stone placement by Lobar subcontractor





Corridor B116







05/31/17 – Lobar subcontractor placed stone subbase in Area B1



05/31/17 – Lobar installed vapor barrier in Area B1









06/02/17 – Lobar placed the concrete slab on grade in the North classrooms of Area B1











05/26/17 – Lobar subcontractor installed CMU foundation walls in Area B2









05/31/17 – Lobar subcontractor placed stone subbase in Area B2









06/01/17 – Boro installing underground feeder conduit from Area B2 to main electrical room in Area C









05/30/17 – Silvertip continued install of underground sanitary piping main down through corridor B123











05/31/17 – Silvertip subcontractor backfill of underground sanitary piping main down through corridor B123









05/23/17 - Lobar subcontractor excavating interior footers in Area C1









05/24/17 – Lobar placing concrete footers in Area C1










05/22/17 – Lobar subcontractor placing perimeter CMU foundation walls in Area C2










Elementary school foundations progress in Area A as of 06/02/17










Elementary school foundations progress in Area B1 as of 06/02/17










Elementary school foundations progress in Area B2 as of 06/02/17









Elementary school foundations progress in Area C as of 06/02/17







Two Week Look Ahead

- Lobar Complete slab on grade in Area B1, Place slab on grade in Area B2, Start 1st floor walls in Area A-East, Continue footers in Area C
- Silvertip Continue under slab sanitary and storm pipe, Interior wall rough-in's in Area A-East, Begin underground sanitary and storm pipe in Area C
- Boro Interior wall rough-in's in Area A-East, Continue underground feeder conduit to main electrical room, Begin under slab conduit in Area C
- Farfield Coordinate install of Area A-East ductwork and pipe rough-ins with wall install



